

Asia Submarine-cable Express (ASE) – Tseung Kwan O

Second Weekly Site Inspection Report

17 October 2012

Environmental Resources Management
16/F DCH Commercial Centre
25 Westlands Road
Quarry Bay, Hong Kong
Telephone 2271 3000
Facsimile 2723 5660

www.erm.com





Asia Submarine-cable Express (ASE) – Tseung Kwan O

**Environmental Resources
Management**

16/F DCH Commercial Centre
25 Westlands Road
Quarry Bay
Hong Kong
Telephone: (852) 2271 3000
Facsimile: (852) 2723 5660
E-mail: post.hk@erm.com
http://www.erm.com

2nd Weekly Site Inspection Report

Document Code: 0171870 Inspection Rpt Flyer Sheet.doc

Client: NTT Com Asia Ltd		GMS No: 0171870			
Summary: This report presents the inspection findings and the implementation status of the EM&A recommendations on environmental protection and pollution control mitigation measures and monitoring.		Date: 17 October 2012			
		Approved by:  Terence Fong Project Director			
0	2 nd Weekly Site Inspection Report	GYANG	GYANG	TFONG	17 Oct 12
Revision	Description	By	Checked	Approved	Date
<p>This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies on the report at their own risk.</p> <p>This report has been prepared by Environmental Resources Management the trading name of 'ERM Hong-Kong, Limited', with all reasonable skill, care and diligence within the terms of the Contract with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client.</p> <p>We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above.</p> <p>This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies on the report at their own risk.</p>		<p>Distribution</p> <p><input checked="" type="checkbox"/> Internal</p> <p><input checked="" type="checkbox"/> Public</p> <p><input type="checkbox"/> Confidential</p>   			

Asia Submarine-cable Express (ASE) – Tseung Kwan O Environmental Certification Sheet EP-433/2011

Reference Document/Plan

Document/ Plan to be Certified / Verified:	Second Site Inspection Report
Date of Report:	17 October 2012
Date prepared by ET:	ERM-Hong Kong Ltd
Date received by IEC:	Ecosystem Ltd

Reference EM&A Manual/ EP Requirement

<p>EM&A Manual Requirement:</p> <p style="text-align: center;">Section 5.1</p> <p><i>Content: Site Inspections</i></p> <p>“...A weekly site inspection will be carried out at the proposed BMH in TKO Industrial Estate until the completion of construction works at the landing point. The areas of inspection will not be limited to the site area and should also include the environmental conditions outside the site which are likely to be affected, directly or indirectly, by the site activities...”</p>
<p>EP Condition:</p> <p style="text-align: center;">Condition No. 2.3</p> <p><i>Content: Buffer to Identified Coral Communities</i></p> <p>“To protect the coral communities at Cape Collinson and Tai Long Pai, the Permit Holder shall confirm the identified coral communities will be more than 180m away from the cable alignment and in any case the IEC of the EM&A Programme shall certify in writing adequate buffer to the identified coral communities are maintained during the cable laying works. ...”</p> <p style="text-align: center;">Condition No. 2.4</p> <p><i>Content: Site Audit</i></p> <p>“To monitor the environmental impacts and timely implementation of the recommended mitigation measures, the Permit Holder shall:</p> <ul style="list-style-type: none"> (i) implement the EM&A programme of the Project in accordance with the procedures and requirements set out in the approved EM&A” (ii) submit to the Direct... (a)...; (b) weekly impact monitoring and site audit report within three days after the relevant monitoring data are collected or become available; and (c)...”

ET Certification

I hereby certify that the above referenced document/~~plan~~ complies with the above referenced condition of EP-433/2011.

A handwritten signature in black ink, appearing to read "Terence Fong".

Terence Fong, Environmental
Team Leader:

Date: 17 October 2012

IEC Verification

I hereby verify that the above referenced document/~~plan~~ complies with the above referenced condition of EP-433/2011.

A handwritten signature in black ink, appearing to read "Vincent Lai".

Dr Vincent Lai, Independent
Environmental Checker:

Date: 17 October 2012

CONTENTS

1	INTRODUCTION	1
1.1	PURPOSE OF THE REPORT	1
1.2	STRUCTURE OF THE REPORT	1
2	PROJECT INFORMATION	2
2.1	BACKGROUND	2
2.2	WORKS PROGRAMME AND WORKS LOCATIONS	2
2.3	CONSTRUCTION ACTIVITIES	3
2.4	STATUS OF ENVIRONMENTAL APPROVAL DOCUMENTS	4
3	ENVIRONMENTAL MONITORING	5
3.1	CABLE INSTALLATION WATER QUALITY MONITORING	5
3.2	MARINE MAMMAL OBSERVATION	5
3.3	CORAL MONITORING	5
3.4	SITE INSPECTION AND AUDIT	6
4	SITE INSPECTION RESULTS	7
5	ENVIRONMENTAL NON-CONFORMANCE	8
5.1	SUMMARY OF ENVIRONMENTAL NON-COMPLIANCE	8
5.2	SUMMARY OF ENVIRONMENTAL COMPLAINT	8
5.3	SUMMARY OF ENVIRONMENTAL SUMMON AND SUCCESSFUL PROSECUTION	8
6	FUTURE KEY ISSUES	9
6.1	KEY ISSUES FOR THE NEXT REPORTING PERIOD	9
6.2	MONITORING SCHEDULE FOR THE NEXT REPORTING PERIOD	9
7	CONCLUSIONS	10

LIST OF TABLES

- Table 2.1 Summary of Landing Point Construction Activities Undertaken during the Reporting Period*
- Table 2.2 Summary of Current Environmental Licensing, Notification and Permit Status*
- Table 6.1 Construction Works to Be Taken For the Next Reporting Week*

LIST OF ANNEXES

- Annex A Proposed ASE Submarine Cable System (Layout Plan)*
- Annex B Location of ASE Landing Point and Terrestrial Cable Route*
- Annex C Completed Site Inspection Log*
- Annex D Photographic Records on Site*

EXECUTIVE SUMMARY

NTT Com Asia (NTTCA) proposes to install a telecommunication cable (Asia Submarine-cable Express (ASE) cable) of approximately 7,200 km in length, connecting Japan and Singapore with branches to the Philippines, Hong Kong SAR (HKSAR) and Malaysia. A Project Profile (PP-452/2011) which includes an assessment of the potential environmental impacts associated with the installation of the submarine telecommunications cable system was prepared and submitted to the Environmental Protection Department (EPD) under section 5.(1)(b) and 5.(11) of the Environmental Impact Assessment Ordinance (EIAO) for the application for Permission to apply directly for Environmental Permit (EP). The Environmental Protection Department, subsequently issued an Environmental Permit (EP- 433/2011).

This is the **Second Weekly Site Inspection Report** that presents the findings of the site inspection and other EM&A activities undertaken during the period from 8 to 14 October 2012.

Environmental Site Inspection

A weekly joint environmental site inspection was carried out by the representatives of the Contractor and the Environmental Team (ET). Environmental performance complied with the environmental requirements and all necessary mitigation measures were properly implemented.

Marine Mammal Observation

Daily marine mammal exclusion zone monitoring was not carried out in the reporting period as the cable installation works in Zone C and from C to the boundary of HKSAR waters has not started.

Coral Monitoring

Impact monitoring for coral during cable installation is not required under the Project. When the cable installation barge passed the identified coral communities/ significant coral habitats presented in the *Baseline Coral Monitoring Survey Report*, the nearest distances between the barge and the coral habitats in Zone A and Zone B were 230m and 270m respectively, indicating the cable alignment of more than 180m away from the corals as required in the Environmental Permit (EP- 433/2011).

Summary of Breaches of Action/Limit Levels

Exceedances in the Action and Limit Levels of bottom DO were recorded in the reporting period. After a careful examination of the monitoring data, it is considered that the observed low DO levels might represent a natural fluctuation in the background levels rather than a result of the Project.

Environmental Complaints, Non-compliance & Summons

No non-compliance with PP recommendations, EP conditions and other requirements associated with the construction of the Project was recorded in the reporting period.

No environmental complaint was received in this reporting period.

No environmental summons was received in this reporting period.

Upcoming Works for the Next Reporting Period

Works to be undertaken in the coming monitoring period include cable laying works in Zone C and from C eastward to the boundary of HKSAR waters, seawall duct work, land duct laying works, beach manhole construction and backfilling and restatement.

Potential environmental impacts arising from the above construction activities are mainly associated with marine water quality, dust, construction noise and waste management.

1 INTRODUCTION

ERM-Hong Kong, Limited (ERM) was appointed by NTT Com Asia (NTTCA) as the Environmental Team to conduct regular site inspections and audit the implementation of all environmental monitoring and mitigation measures recommended in the Project Profile (PP) (Register No. PP - 452/2011) for the Proposed Asia Submarine-cable Express (ASE) – Tseung Kwan O (the Project).

1.1 PURPOSE OF THE REPORT

This is the **Second Weekly Site Inspection Report** (the Report), which summarises the inspection findings for the period from **8 October 2012** to **14 October 2012** and the implementation status of the EM&A recommendations on environmental protection and pollution control mitigation measures and monitoring.

1.2 STRUCTURE OF THE REPORT

The structure of the Report is as follows:

Section 1 : **Introduction**

Details the scope and structure of the Report.

Section 2 : **Project Information**

Summarises background and scope of the Project, site description, construction programme, the construction works undertaken and the status of Environmental Permits/Licenses during the reporting period.

Section 3 : **Environmental Monitoring**

Summarises the monitoring programmes as recommended in the PP and the monitoring undertaken during the reporting period.

Section 4 : **Site Inspection Results**

Summarises the findings of the weekly site inspection undertaken within the reporting period.

Section 5 : **Environmental Non-conformance**

Summarises any exceedances of environmental performance standard, environmental complaints and environmental summons received within the reporting period.

Section 6 : **Upcoming Works for the next Reporting Period**

Summarises the impact forecast and monitoring schedule for the next reporting week.

Section 7 : **Conclusions**

2.1**BACKGROUND**

NTT Com Asia (NTTCA) proposes to install a telecommunication cable (Asia Submarine-cable Express (ASE) cable) of approximately 7,200 km in length, connecting Japan and Singapore with branches to the Philippines, Hong Kong SAR (HKSAR) and Malaysia. NTTCA is responsible for securing the approval to land the ASE cable in Tseung Kwan O, Hong Kong SAR (HKSAR). The proposed landing site will be at a new Beach Manhole (BMH) and ultimately connect with a Data Centre in Tseung Kwan O (TKO) Industrial Estate which is scheduled for completion in 2012. From Tseung Kwan O, the cable will extend eastward approaching the Tathong Channel. Near to Cape Collinson, the cable is approximately parallel to the Tathong Channel until north of Waglan Island where the cable travels eastward to the boundary of HKSAR waters where it enters the South China Sea. The total length of cable in Hong Kong SAR waters is approximately 33.5 km. A map of the proposed cable route is presented in *Annex A*.

A Project Profile (PP-452/2011) which includes an assessment of the potential environmental impacts associated with the installation of the submarine telecommunications cable system was prepared and submitted to the Environmental Protection Department (EPD) under section 5.(1)(b) and 5.(11) of the Environmental Impact Assessment Ordinance (EIAO) for the application for Permission to apply directly for Environmental Permit (EP). The Environmental Protection Department, subsequently issued an Environmental Permit (EP- 433/2011).

Under the requirements of Condition 2.4 of the EP, an EM&A programme as set out in the revised Environmental Monitoring and Audit Manual (EM&A Manual) is required to be implemented. The EM&A programme includes water quality monitoring, marine mammal observation, coral monitoring and weekly site inspection.

2.2**WORKS PROGRAMME AND WORKS LOCATIONS**

The location of the cable installation works within the boundary of Hong Kong SAR waters is shown in *Annex A*, while the location of the landing point (ie new Beach Manhole (BMH) in TKO Industrial Estate) is shown in *Annex B*. The preliminary construction programme of the Project is given in *Figure 2.1*.

Figure 2.1 Preliminary Construction Programme

	Week											
	1	2	3	4	5	6	7	8	9	10	11	12
Submarine Cable Installation												
Zone A												
Zone B												
Zone C												
Outside Zone C to HK Boundary												
Post-installation Works												
Diver Jetting												
Landing Point Construction												
Preparation Work												
Seawall Duct Work												
Land Duct Laying												
Beach Manhole Construction												
Reinstatement												

2.3 CONSTRUCTION ACTIVITIES

Submarine Cable Installation

The submarine-cable installation works started on 8 October 2012. By the end of the reporting period (ie 14 October 2012), cable installation works in Zone A and Zone B had been large finished.

Landing Point Construction

The construction works of the landing point commenced on 4 October 2012 and are temporarily scheduled to be completed in early December of 2012. A summary of the major construction activities undertaken on the landing point during the reporting period is shown in *Table 2.1*.

Table 2.1 Summary of Landing Point Construction Activities Undertaken during the Reporting Period

Construction Activities Undertaken
• Levelling of base soil at seawall
• Excavation of base soil at sea bed
• Levelling of base soil at sea bed
• Installation of GI pipe at seawall

2.4

STATUS OF ENVIRONMENTAL APPROVAL DOCUMENTS

A summary of the relevant permits, licences, and/or notifications on environmental protection for this Project is presented in *Table 2.2*.

Table 2.2 *Summary of Current Environmental Licensing, Notification and Permit Status*

Permit/ Licences/ Notification	Reference	Validity Period	Remarks
Environmental Permit	EP-433/2011	Throughout the construction and operation of the Project	Permit granted on 20 December 2011
Construction Noise Permit	GW-RE0774-12	18 Sep 2012 – 31 Jan 2013	Permits granted on using of registered powered mechanical equipment for 07:00-23:00 hrs on general holidays (including Sundays) and 19:00-23:00 hrs on any day not being a general holiday for Sub-marine cable laying works of the Project

3 ENVIRONMENTAL MONITORING

3.1 CABLE INSTALLATION WATER QUALITY MONITORING

Baseline water quality monitoring was completed by the end of September 2012. Baseline Water Quality Monitoring Reports for Zone A, Zone B and Zone C were submitted on 19 September 2012, 25 September 2012 and 1 October 2012, respectively.

Impact water quality monitoring was conducted daily from 8 Oct 2012 to 14 Oct 2012 as the cable installation works proceeded in Zone A and Zone B. Exceedances in the Action and Limit Levels of bottom DO were recorded in the reporting period. After a careful examination of the monitoring data, it is considered that the observed low DO levels might represent a natural fluctuation in the background levels rather than a result of the Project. Relevant water quality monitoring results of the reporting period and mitigation measures to control water quality pollution as recommended in the PP will be presented in the *First Weekly Water Quality Impact Monitoring Report* within three days after the relevant monitoring data are collected.

3.2 MARINE MAMMAL OBSERVATION

Daily marine mammal exclusion zone monitoring is required to be conducted during the cable installation works taking place in daylight hours along the section outside Zone A to Zone B (ie Zone C and from C to the boundary of HKSAR waters). This monitoring was not carried out in the reporting period as the cable installation works in Zone C and from C to the boundary of HKSAR waters has not started.

3.3 CORAL MONITORING

Baseline coral monitoring was completed in September 2012. The Baseline Coral Monitoring Survey Report was submitted on 28 September 2012. Post-project coral monitoring will be conducted within one month after completion of the jetting works, with the Post-project Coral Monitoring Survey Report to be submitted within one month after completion of the marine works. Impact monitoring for coral during cable installation works is not required under the Project.

When the cable installation barge passed the identified coral communities/ significant coral habitats presented in the *Baseline Coral Monitoring Survey Report*, the nearest distances between the barge and the coral habitats in Zone A and Zone B were 230m and 270m respectively, indicating the cable alignment of more than 180m away from the corals as required in the Environmental Permit (EP- 433/2011).

3.4

SITE INSPECTION AND AUDIT

In accordance with the revised EM&A Manual, a weekly site inspection should be undertaken at the landing point (ie new Beach Manhole (BMH) in TKO Industrial Estate) to ensure that the appropriate environmental protection and pollution control mitigation measures are properly implemented in accordance with the Project Profile (PP-452/2011). Results of the site inspection in the reporting period are provided in *Section 4*.

The weekly site inspection is required to be carried out by the representatives of the Contractor and the Environmental Team (ET). A Site Inspection Log is completed by the ET representative to record whether the Contractor is compliant with environmental regulations in terms of noise, water quality and housekeeping etc (*Annex C*).

During the reporting period, the site inspection was conducted on 12 October 2012 by the representatives of the Contractor and the ET. There was no non-compliance recorded during the site audit. Major findings and recommendations are summarised as follows:

- (i) A copy of EP was displayed conspicuously at the vehicular site entrance in accordance with the requirement of Condition 1.5 of the EP.
- (ii) A silt curtain was employed around the seawall area in order to reduce the dispersion of sediments from the landing site (*Annex D Photo No. 1*).
- (iii) During the site inspection, rubbish bins could not be found within the construction site. The Contractor was reminded to provide rubbish bins on site and to educate the workers to dispose rubbish properly. Follow-up actions were conducted in the next day by the Contractor and a rubbish bin was placed on site (*Annex D Photo No. 2*).
- (iv) Tarpaulin sheets, which should be used to cover unpaved slopes and dusty stockpiles to prevent dust generation or erosion, were observed to be missing on the construction site (*Annex D Photo No. 3*). The Contractor was recommended to cover the stockpiles properly to prevent excessive dust generation. Corrective action was conducted by the Contractor in the following day (*Annex D Photo No. 4*).
- (v) The Contractor was nevertheless advised to spray water to all exposed earth surfaces within the construction site regularly for the purpose of dust suppression.

5 *ENVIRONMENTAL NON-CONFORMANCE*

5.1 *SUMMARY OF ENVIRONMENTAL NON-COMPLIANCE*

No non-compliance of PP/ EM&A/ EP/ legislative requirements was recorded during the reporting period.

5.2 *SUMMARY OF ENVIRONMENTAL COMPLAINT*

No complaint was received during the reporting period.

5.3 *SUMMARY OF ENVIRONMENTAL SUMMON AND SUCCESSFUL PROSECUTION*

No summons was received during the reporting period.

6 FUTURE KEY ISSUES

6.1 KEY ISSUES FOR THE NEXT REPORTING PERIOD

Works to be taken for the next reporting period are summarised in *Table 6.1*.

Table 6.1 *Construction Works to Be Taken For the Next Reporting Week*

Work to be taken
<i>Submarine Cable Installation</i>
<ul style="list-style-type: none">• Cable laying works in Zone C and from C eastward to the boundary of HKSAR waters
<i>Landing Point Construction</i>
<ul style="list-style-type: none">• Seawall duct work• Land duct laying works• Beach manhole construction• Backfilling and reinstatement

Potential environmental impacts arising from the above construction activities are mainly associated with marine water quality, dust, construction noise and waste management.

6.2 MONITORING SCHEDULE FOR THE NEXT REPORTING PERIOD

Daily impact water quality monitoring will be continued in next week until the completion of the cable installation works in Zone C. The results will be summarised in the *Second Weekly Water Quality Impact Monitoring Report* after the relevant monitoring data become available.

Next weekly site inspection is temporarily scheduled on 19 October 2012.

This **Second Weekly Site Inspection Report** presents the findings of the site inspection and other EM&A activities undertaken during the period from **8 to 14 October 2012**, in accordance with the PP (Register No. PP - 452/2011), revised EM&A Manual and the requirements of Environmental Permit (EP-433/2011).

Submarine-cable installation works/ jetting works were conducted in Zone A and Zone B during the reporting period. Impact water quality monitoring was hence carried out daily from 8 Oct 2012 to 14 Oct 2012 as the cable installation works proceeded. Exceedances in the Action and Limit Levels of bottom DO were recorded, but it is considered that the observed low DO levels might represent a natural fluctuation in the background levels rather than a result of the Project.

When the cable installation barge passed the identified coral communities/ significant coral habitats presented in the *Baseline Coral Monitoring Survey Report*, the nearest distances between the barge and the coral habitats in Zone A and Zone B were 230m and 270m respectively, indicating the cable alignment of more than 180m away from the corals as required in the Environmental Permit (EP- 433/2011).

A weekly joint environmental site inspection was conducted on 12 October 2012 during the reporting period. It confirmed that the environmental mitigation measures recommended in the PP were properly implemented by the Contractor.

No non-compliance event was recorded during the reporting period.


No complaint and summons/prosecution was received during the reporting period.

The ET will keep track on the construction works to confirm compliance of environmental requirements and the proper implementation of all necessary mitigation measures.

Annex A

Proposed ASE Submarine Cable System (Layout Plan)

WLCP	Easting	Northing	WLCP	Easting	Northing	WLCP	Easting	Northing	WLCP	Easting	Northing
1	845589	815898	15	844806	813421	29	846105	810106	43	853937	807906
2	845556	815867	16	844828	813369	30	846299	809865	44	857849	808794
3	845385	815868	17	844828	813180	31	846902	809359	45	858608	809583
4	845286	815875	18	844828	812582	32	846940	809327	46	860721	811777
5	845185	815882	19	844901	812548	33	846957	809313	47	861931	812293
6	845029	815818	20	844963	812519	34	847261	809058	48	865089	812773
7	844903	815767	21	844965	812516	35	847395	808872	49	866482	813071
8	844645	815255	22	845068	812338	36	847494	808734	50	867598	813533
9	844332	814636	23	845243	812143	37	848072	807931	51	868096	813543
10	844358	814533	24	845620	810966	38	848237	807897	52	868723	813544
11	844432	814234	25	845742	810585	39	848831	807778	53	869831	813538
12	844534	814088	26	845799	810409	40	850650	807902			
13	844579	813976	27	845866	810200	41	852671	808041			
14	844711	813653	28	845958	810164	42	853316	808085			



Key

- Work Limit Control Point (WLCP)
- ASE Submarine Cable System
- District Boundary

Annex A

ASE Submarine Cable System (Layout Plan)

**Environmental
Resources
Management**




File: T:\GIS\CONTRACT\0171870\Mxd\0171870_Landing_Overview_20110815.mxd
Date: 10-Oct-2012

Annex B

Location of ASE Landing Point and Terrestrial Cable Route



Key

 Beach Manhole

 ASE Terrestrial Cable Route



Proposed BMH



Annex C

Completed Site Inspection Log

Site: ASE-Tseung Inspected By: Girard YANLI
 Inspection Date: 12/10/12 Time: 16:00 - 17:00

Weather

Condition Sunny Fine Overcast Drizzle Rain Storm Hazy
 Temperature 29 °C Humidity High Moderate Low
 Wind Calm Light Breeze Strong

A Noise

	N/A or not observed	Yes	No	Photo/Remarks
A1 Are all plant and equipment well maintained and in good operating condition?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
A2 Is idle equipment turned off or throttled down?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
A3 Are powered mechanical equipment covered or shielded by acoustic materials?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
A4 Are silenced equipment used where practicable?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
A5 Do mobile plants be sited as far away from NSRs as possible?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
A6 Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
A7 Major noise source(s)	<input checked="" type="checkbox"/> Construction activities inside of site			
	<input type="checkbox"/> Traffic			
	<input type="checkbox"/> Construction activities outside of site			
	<input type="checkbox"/> Others			
A8 Any remedial action undertaken?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

B Water Quality

	N/A or not observed	Yes	No	Photo/Remarks
B1 Is drainage system adequate? Are there temporary ditches for runoff discharge into appropriate	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B2 Watercourse?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B3 With silt retention pond?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B4 Do permanent drainage channels have: sediment basin?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Silt Curtain available in front of the seaball opening point.
B5 traps and baffles?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B6 Are there sediment tanks for settling runoff prior to disposal?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B7 Are there oil interceptors in drainage system?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B8 Oil and grease removed regularly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B9 Bypass to prevent flushing during periods of heavy rain?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B10 Is drainage system well maintained?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B11 Is exposed earth stabilized after earthworks have been completed?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Not completed yet.
B12 Are exposed slope surfaces covered (by tarpaulin or other means)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B13 Are open stockpiles of more than 20 m ³ covered during rainstorm?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	See Note 1
B14 Are manholes covered and sealed?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Rainy Season				
B15 Drainage system adequately designed for storm flow?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Construction carried out in the dry season
B16 Sediment control measures inspected and maintained after rain storms?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B17 Is debris and rubbish on site collected and disposed of properly?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	See Note 2
B18 Is wastewater discharge license available for inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
B19 Measures to prevent the washing away of sand/silt to drains?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
B20 Is there any sediment plume observed existing the marine works area?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

C Environmental Complaint

C1 Number of Environmental Complaint Received from 8 Oct to 14 Oct 2012 _____

D General / Housekeeping

	N/A or not observed	Yes	No	Photo/Remarks
D1 Are potential stagnant pools cleared and mosquito breeding prevented?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>No stagnant pools on site</u>

Items for Inspection

- Seawall opening point
- Land duct alignment
- Construction material storage area.

Notes / Issues Recorded On Site

1. Open stockpiles/excavated boulders and rocks were found without covers. The Contractor was reminded stockpiles of dusty materials on site should be covered with tarpaulin or similar fabric to prevent excessive dust generation.
2. No rubbish bin was observed to be available on site. The Contractor was reminded to provide rubbish bin on site and educate the workers to dispose rubbish properly.

Corrective Actions

182. Corrective actions were conducted by the Contractor in the next day. Covering sheet was provided to open dusty stockpiles. Rubbish bin was placed within construction site.

Signatures:

ET:



(Name: _____)

Grace YAN

Annex D

Photographic Records on Site



Photo 1 - A silt curtain was employed around the seawall area.



Photo 2 - A rubbish bin was placed on site in the next day of site inspection.



Photo 3 - Tarpaulin sheets to cover dusty stockpiles to prevent dust generation were absent from the construction site.



Photo 4 - The corrective action to cover dusty materials was conducted by the Contractor in the following day of site inspection.

ERM has over 140 offices
Across the following
countries worldwide

Argentina	New Zealand
Australia	Panama
Belgium	Peru
Brazil	Poland
Canada	Portugal
China	Puerto Rico
Colombia	Romania
France	Russia
Germany	Singapore
Hong Kong	South Africa
Hungary	Spain
India	Sweden
Indonesia	Taiwan
Ireland	Thailand
Italy	The Netherlands
Japan	United Arab Emirates
Kazakhstan	United Kingdom
Korea	United States
Malaysia	Vietnam
Mexico	

Environmental Resources Management

**16/F DCH Commercial Centre
25 Westlands Road
Quarry Bay, Hong Kong**

T: 2271 3000

F: 2723 5660

www.erm.com

