Site	ASE Tseung Kwan O Landing Point	Inspected By:						
Insp	ection Date: 28-Feb-13 Time: 14:00 -1	Grace YANG 4:30						
Weather								
Con	Condition Sunny Fine V Overcast Drizzle Rain Storm Hazy							
Tem	perature 20 °C Humidity High	✓ Moderate Low						
Wind Calm Light Breeze Strong								
Α	Noise	N/A or Yes No Photo/Remarks not observed						
A1	Are all plant and equipment well maintained and in good operating condition?							
A2	Is idle equipment turned off or throttled down?	<u> </u>						
А3	Are powered mechanical equipment covered or shielded by acoustic materials?							
A4	Are silenced equipment used where practicable?							
A5	Do mobile plants be sited as far away from NSRs as possible?	✓ No NSRs nearby.						
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?	✓ No NSRs nearby.						
A7	Major noise source(s) Traffic	Construction activities inside of site						
	Construction activities outside of site	Others No construction activities in process.						
A8	Any remedial action undertaken?	✓						

Rev1 Page 1 of 3

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
B1	Is drainage system adequate?		✓			B1 - B10:
	Are there temporary ditches for runoff discl	narge into appropriate				
B2	Watercourse?		✓			Silt curtain
ВЗ	With silt retention pond?		√			decommissioned as
B4	Do permanent drainage channels have:	sediment basin?	✓			construction works at the
B5		traps and baffles?	✓			seawall side finished.
В6	Are there sediment tanks for settling runoff	prior to disposal?	✓			
В7	Are there oil interceptors in drainage system	m?	✓			
В8	Oil and grease removed regularly?		\checkmark			
В9	Bypass to prevent flushing during per	iods of heavy rain?	\checkmark			
B10	Is drainage system well maintained?		✓			
B11	Is exposed earth stabilized after earthwork	s have been completed?		✓		
B12	Are exposed slope surfaces covered (by ta	rpaulin or other means)?	✓			
B13	Are open stockpiles of more than 20 m ³ co	vered during rainstorm?	✓			
B14	Are manholes covered and sealed?			✓		
	Rainy Season					
B15	Drainage system adequately designed	d for storm flow?	\checkmark			B15 & B16: Inspection
B16	Sediment control measures inspected rain storms?	and maintained after	✓			conducted in dry season.
B17	Is debris and rubbish on site collected and	disposed of properly?		√		
B18	Is wastewater discharge license available f	or inspection?	✓			
B19	Measures to prevent the washing away of	sand/silt to drains?	✓			
B20	Is there any sediment plume observed exist	ting the marine works area?			√	

Rev1 Page 2 of 3

	Environmental Complaint						
1	Number of Environmental Complaint Received from	22-Feb-13	_to	28-Fel	o-13 .	0	
	General / Housekeeping		no	N/A or ot observed	Yes	No	Photo/Remarks
1	Are potential stagnant pools cleared and mosquito breeding prevented?			√			
	Items for Inspection						
	- New beach manhole, and - Land duct construction site						
	Notes / Issues Recorded On Site						
	Nil.						
	Corrective Actions						
	Nil.						
	Signatures: ET:						
	(Name: Grace YANG)						

Rev1 Page 3 of 3