Site:	Tseung Kwan O Landing Point	Inspected By: Grace YANG				
Inspection Date: 15-Nov-12 Time: 16:00 - 1						
Wea	ather	_				
Condition Sunny Fine ✓ Overcast Drizzle		Rain Storm Hazy				
Temperature 23 °C Humidity High		Moderate ✓ Low				
Wind Calm Light Breeze Strong						
Α	Noise	N/A or Yes No Photo/Remarks not observed				
A1	Are all plant and equipment well maintained and in good operating condition?					
A2	Is idle equipment turned off or throttled down?					
А3	Are powered mechanical equipment covered or shielded by acoustic materials?					
A4	Are silenced equipment used where practicable?					
A5	Do mobile plants be sited as far away from NSRs as possible?	✓ No NSRs nearby.				
A6	Do plants known to emit noise strongly in one direction be oriented awa from nearby NSRs?	y No NSRs nearby.				
A7	Major noise source(s) Traffic	✓ Construction activities inside of site				
	Construction activities outside of site	Others				
A8	Any remedial action undertaken?					

Rev1 Page 1 of 4

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
В1	Is drainage system adequate?		✓			B1 - B10:
	Are there temporary ditches for runoff discl	narge into appropriate				
B2	Watercourse?		✓			Silt curtain
ВЗ	With silt retention pond?		✓			decommissioned as
B4	Do permanent drainage channels have:	sediment basin?	√			construction works at the
B5		traps and baffles?	✓			seawall side finished.
B6	Are there sediment tanks for settling runoff	prior to disposal?	✓			No site runoff generated
B7	Are there oil interceptors in drainage syste	m?	✓			by the time of inspection
B8	Oil and grease removed regularly?		✓			
В9	Bypass to prevent flushing during per	iods of heavy rain?	✓			
B10	Is drainage system well maintained?		✓			
B11	Is exposed earth stabilized after earthwork	s have been completed?	✓			Not completed yet.
B12	Are exposed slope surfaces covered (by ta	rpaulin or other means)?	✓			
B13	Are open stockpiles of more than 20 m ³ co	vered during rainstorm?	✓			No rainstorm occurred.
B14	Are manholes covered and sealed?		✓			
	Rainy Season					
B15	Drainage system adequately designed	d for storm flow?	✓			B15 & B16: Inspection
B16	Sediment control measures inspected rain storms?	I and maintained after	✓			conducted in dry season.
B17	Is debris and rubbish on site collected and	disposed of properly?		✓		
B18	Is wastewater discharge license available f	or inspection?	✓			
B19	Measures to prevent the washing away of	sand/silt to drains?	√			
B20	Is there any sediment plume observed exist	sting the marine works area?			✓	

Rev1 Page 2 of 4

Environmental Complaint
Number of Environmental Complaint Received from 12-Nov-12 to 18-Nov-12 . 0
General / Housekeeping N/A or Yes No Photo/Remarks not observed
Are potential stagnant pools cleared and mosquito breeding
Items for Inspection
- New beach manhole; - Land duct construction site; and - Storage area for construction materials.
Notes / Issues Recorded On Site
1. Stockpiles of the excavated materials from the proposed beach manhole were observed to be exposed. To avoid dust generation, the Contractor was recommended to spray water on the exposed surfaces regularly or to cover those stockpiles with plastic sheeting / tarpaulin before they are backfilled / reused.

Rev1 Page 3 of 4

(Name: Grace YANG

Corrective Actions
Follow-up actions by the Contractor will be checked in next week's site inspection.
Signatures: ET:

Rev1 Page 4 of 4