Site: ASE Tseung Kwan O Landing Point Inspected By: Grace YANG						
Insp	pection Date: 21-Dec-12 Time: 09:00 - 0)9:30	j L	Grace 17	ANG	
We	ather					
Con	Condition Sunny Fine VOvercast Drizzle Rain Storm Hazy					
Tem	Temperature 18 °C Humidity High ✓ Moderate Low					
Win	d Calm Light Breeze Strong					
Α	Noise	N/A or not observed	Yes	No	Photo/Remarks	
A1	Are all plant and equipment well maintained and in good operating condition?	✓				
A2	Is idle equipment turned off or throttled down?	✓				
А3	Are powered mechanical equipment covered or shielded by acoustic materials?	✓				
A4	Are silenced equipment used where practicable?	✓				
A5	Do mobile plants be sited as far away from NSRs as possible?	\checkmark			No NSRs nearby.	
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?	/ ✓			No NSRs nearby.	
A7	Major noise source(s) Traffic	Constructi	on activit	ies inside o	f site	
	Construction activities outside of site	✓ Others	No con	struction act	tivities in process.	
A8	Any remedial action undertaken?	✓				

Rev1 Page 1 of 3

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality	N/A or not observed	Yes	No	Photo/Remarks
В1	Is drainage system adequate?	✓			B1 - B10:
	Are there temporary ditches for runoff discharge into appropriate				
B2	Watercourse?	✓			Silt curtain
ВЗ	With silt retention pond?	√			decommissioned as
B4	Do permanent drainage channels have: sediment basin?	✓			construction works at the
B5	traps and baffles?	\checkmark			seawall side finished.
В6	Are there sediment tanks for settling runoff prior to disposal?	\checkmark			
В7	Are there oil interceptors in drainage system?	✓			
B8	Oil and grease removed regularly?	\checkmark			
В9	Bypass to prevent flushing during periods of heavy rain?	\checkmark			
B10	Is drainage system well maintained?	✓			
B11	Is exposed earth stabilized after earthworks have been completed?		✓		
B12	Are exposed slope surfaces covered (by tarpaulin or other means)?	✓			
B13	Are open stockpiles of more than 20 m ³ covered during rainstorm?	\checkmark			
B14	Are manholes covered and sealed?	\checkmark			
	Rainy Season				
B15	Drainage system adequately designed for storm flow?	✓			B15 & B16: Inspection
B16	Sediment control measures inspected and maintained after rain storms?	✓			conducted in dry season.
B17	Is debris and rubbish on site collected and disposed of properly?		\checkmark		
B18	Is wastewater discharge license available for inspection?	\checkmark			
B19	Measures to prevent the washing away of sand/silt to drains?		✓		
B20	Is there any sediment plume observed existing the marine works area?			\checkmark	

Rev1 Page 2 of 3

Environmental Complaint
Number of Environmental Complaint Received from 17-Dec-12 to 23-Dec-12 . 0
General / Housekeeping N/A or Yes No Photo/Remarks not observed
Are potential stagnant pools cleared and mosquito breeding prevented?
Items for Inspection
- New beach manhole, and - Land duct construction site
Notes / Issues Recorded On Site
Nil.
Corrective Actions
Nil.
Signatures: ET: (Name: Grace YANG)

Rev1 Page 3 of 3