

*Photo 1 – Construction of the new beach manhole has been finished and the site has been reinstated to its original conditions.* 



Photo 3 – Artificial Seawall in front of the cable landing point has been reinstated to its original conditions.



Photo 2 – Construction of the land duct has been finished and the site has been reinstated to its original conditions.



*Photo 4 – Areas in vicinity of the cable landing point have been cleaned.*