		_			
Site:	Tseung Kwan O Landing Point ection Date: 23-Nov-12 Time: 14:15 - 1	Inspected By: Grace YANG			
msp	ection Date. 23-Nov-12 1iiile. 14.15 -	15.00			
Wea	Weather				
Condition Sunny Fine Overcast Drizzle		Rain Storm Hazy			
Temperature 22 °C Humidity High		Moderate ✓ Low			
Wind Calm Light Breeze Strong					
Α	Noise	N/A or Yes No Photo/ not observed	Remarks		
A1	Are all plant and equipment well maintained and in good operating condition?	✓ See N	ote 1		
A2	Is idle equipment turned off or throttled down?				
АЗ	Are powered mechanical equipment covered or shielded by acoustic materials?				
A4	Are silenced equipment used where practicable?	<pre>/</pre>			
A5	Do mobile plants be sited as far away from NSRs as possible?	✓	Rs nearby.		
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?		Rs nearby.		
A7	Major noise source(s) Traffic	✓ Construction activities inside of site			
	Construction activities outside of site	Others			
A8	Any remedial action undertaken?				

Rev1 Page 1 of 4

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
B1	Is drainage system adequate?		✓			B1 - B10:
	Are there temporary ditches for runoff disc	harge into appropriate				
B2	Watercourse?		✓			Silt curtain
ВЗ	With silt retention pond?		✓		一	decommissioned as
B4	Do permanent drainage channels have:	sediment basin?	✓		一	construction works at the
B5		traps and baffles?	✓			seawall side finished.
B6	Are there sediment tanks for settling runoff	f prior to disposal?	✓			
B7	Are there oil interceptors in drainage syste	m?	\checkmark			
B8	Oil and grease removed regularly?		✓			
B9	Bypass to prevent flushing during per	riods of heavy rain?	✓			
B10	Is drainage system well maintained?		✓			
B11	Is exposed earth stabilized after earthwork	s have been completed?	✓			Not completed yet.
B12	Are exposed slope surfaces covered (by ta	arpaulin or other means)?	✓			
B13	Are open stockpiles of more than 20 m^3 co	overed during rainstorm?			✓	See Note 2
B14	Are manholes covered and sealed?		✓			
	Rainy Season					
B15	Drainage system adequately designe	d for storm flow?	✓			B15 & B16: Inspection
B16	Sediment control measures inspected rain storms?	d and maintained after	✓			conducted in dry season.
B17	Is debris and rubbish on site collected and	disposed of properly?		✓		
B18	Is wastewater discharge license available	for inspection?	✓			
B19	Measures to prevent the washing away of	sand/silt to drains?			✓	See Note 2
B20	Is there any sediment plume observed exist	sting the marine works area?			✓	

Rev1 Page 2 of 4

;	Environmental Complaint
1	Number of Environmental Complaint Received from 19-Nov-12 to 25-Nov-12 . 0
)	General / Housekeeping N/A or Yes No Photo/Remarks not observed
1	Are potential stagnant pools cleared and mosquito breeding prevented? Site inspection was conducted during ra
	Items for Inspection
	- New beach manhole; - Land duct construction site; and - Storage area for construction materials.
	Notes / Issues Recorded On Site
	1. Dark smoke was seen rising from the crane truck used to translocate the excavated rocks and soils. The Contractor was reminded to well maintain all plants and equipment on site. Dark smoke, which indicates inefficient combustion of fuel within the plant engine, should be avoided to minimise air pollution emission. 2. Stockpiles of the excavated soils from the new beach manhole were observed to be exposed during the rain. The Contractor was reminded to cover the stockpiles during rain events to prevent storm runoff, which transports the sediment and eventually deposit it in nearby sea water, storm drains or low-lying areas.

Rev1 Page 3 of 4

(Name: Grace YANG

Corrective Actions
Follow-up actions by the Contractor will be checked in next week's site inspection.
Signatures: ET:

Rev1 Page 4 of 4