Site: ASE Tseung Kwan O Landing Point		Inspected By:			
Inspection Date: 25-Apr-13 Time: 14:00 -14:		4:30 Stacey Tsang			
Wea	ather				
Condition Sunny Fine Overcast Drizzle		Rain Storm Hazy			
Temperature 29 ℃ Humidity High		✓ Moderate Low			
Win	d Calm Light ✓ Breeze Strong				
Α	Noise	N/A or Yes No Photo/Remarks not observed			
A1	Are all plant and equipment well maintained and in good operating condition?				
A2	Is idle equipment turned off or throttled down?				
A3	Are powered mechanical equipment covered or shielded by acoustic materials?				
A4	Are silenced equipment used where practicable?				
A5	Do mobile plants be sited as far away from NSRs as possible?	✓ No NSRs nearby.			
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?	✓ No NSRs nearby.			
A7	Major noise source(s) Traffic	Construction activities inside of site			
	Construction activities outside of site	Others			
A8	Any remedial action undertaken?				

в	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
B1	Is drainage system adequate?		\checkmark			
	Are there temporary ditches for runoff disc	narge into appropriate				
B2	Watercourse?		\checkmark			
B3	With silt retention pond?		\checkmark			
B4	Do permanent drainage channels have:	sediment basin?	\checkmark			
B5		traps and baffles?	\checkmark			
B6	Are there sediment tanks for settling runoff	prior to disposal?	\checkmark			
B7	Are there oil interceptors in drainage syste	m?	\checkmark			
B8	Oil and grease removed regularly?		\checkmark			
B9	Bypass to prevent flushing during per	ods of heavy rain?	\checkmark			
B10	Is drainage system well maintained?		\checkmark			
B11	Is exposed earth stabilized after earthwork	s have been completed?	\checkmark			
B12	Are exposed slope surfaces covered (by ta	rpaulin or other means)?	\checkmark			
B13	Are open stockpiles of more than 20 $\ensuremath{\text{m}}^3$ co	vered during rainstorm?	\checkmark			
B14	Are manholes covered and sealed?			\checkmark		
	Rainy Season					
B15	Drainage system adequately designed	d for storm flow?	\checkmark			
B16	Sediment control measures inspected rain storms?	l and maintained after	\checkmark			
B17	Is debris and rubbish on site collected and	disposed of properly?		\checkmark		
B18	Is wastewater discharge license available f	or inspection?	\checkmark			
B19	Measures to prevent the washing away of s	sand/silt to drains?	\checkmark			
B20	Is there any sediment plume observed exis	ting the marine works area?			\checkmark	

Asia Submarine-cable Express (ASE) - Tseung Kwan O

C Environmental Complaint

C1	Number of Environmental Complaint Received from 22-Apr	-13	to _	28-Ap	r-13	0	
D	General / Housekeeping		-	I/A or observed	Yes	No	Photo/Remarks
D1	Are potential stagnant pools cleared and mosquito breeding prevented?		[\checkmark	Photo 4 Note D1

Items for Inspection				
- Beach Manholes fence Constuction Work				
Notes / Issues Recorded On Site				
D1: A big bucket of water was observed in use on site (photo 4), contractor has been advised to cover it after use to prevent mosquito breeding.				
Corrective Actions				
Nil.				
Signatures: ET: <i>Total</i>				
(Name: Stacey TSANG)				