0:4	Tarana Kura O Landina Daint	Instructed Day				
Site:	Tseung Kwan O Landing Point	Inspected By:				
Insp	ection Date: 26-Oct-12 Time: 14:00 -	Grace YANG 14:30				
Wea	Weather					
Condition Sunny Fine Overcast Drizzle		Rain Storm Hazy				
Temperature 28 °C Humidity ✓ High		Moderate Low				
Win	d Calm Light Breeze Strong					
Α	Noise	N/A or Yes No Photo/Remarks not observed				
A1	Are all plant and equipment well maintained and in good operating condition?	See Note 1				
A2	Is idle equipment turned off or throttled down?					
А3	Are powered mechanical equipment covered or shielded by acoustic materials?					
A4	Are silenced equipment used where practicable?	✓				
A5	Do mobile plants be sited as far away from NSRs as possible?	✓				
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?					
Α7	Major noise source(s) Traffic	Construction activities inside of site				
	Construction activities outside of site	Others				
A8	Any remedial action undertaken?					

Rev1 Page 1 of 4

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
B1	Is drainage system adequate?		✓			B1 - B10:
	Are there temporary ditches for runoff dis	scharge into appropriate				
B2	Watercourse?		\checkmark			Silt curtain was
ВЗ	With silt retention pond?		✓			employed in front of
B4	Do permanent drainage channels have:	sediment basin?	✓			the new beach manhole.
B5		traps and baffles?	✓			
B6	Are there sediment tanks for settling rund	off prior to disposal?	\checkmark			
В7	Are there oil interceptors in drainage sys	tem?	\checkmark			
В8	Oil and grease removed regularly?		✓			
В9	Bypass to prevent flushing during p	eriods of heavy rain?	✓			
B10	Is drainage system well maintained?		\checkmark			
B11	Is exposed earth stabilized after earthwo	rks have been completed?	\checkmark			Not completed yet.
B12	Are exposed slope surfaces covered (by	tarpaulin or other means)?	\checkmark			
B13	Are open stockpiles of more than 20 m^3	covered during rainstorm?		✓		
B14	Are manholes covered and sealed?		✓			
	Rainy Season					
B15	Drainage system adequately design	ned for storm flow?	\checkmark			B15 & B16: Inspection
B16	Sediment control measures inspect rain storms?	ed and maintained after	✓			conducted in dry season.
B17	Is debris and rubbish on site collected ar	nd disposed of properly?		✓		
B18	Is wastewater discharge license available	e for inspection?	✓			
B19	Measures to prevent the washing away of	of sand/silt to drains?	✓			
B20	Is there any sediment plume observed ex	xisting the marine works area?			✓	

Rev1 Page 2 of 4

Environmental Complaint
Number of Environmental Complaint Received from 22-Oct-12 to to 0
General / Housekeeping N/A or Yes No Photo/Remarks not observed
Are potential stagnant pools cleared and mosquito breeding Not applicable due to rain during insepct
Items for Inspection
- Sea wall opening point / new beach manhole; - Land duct construction site; and - Storage area for construction materials.
Notes / Issues Recorded On Site
Dark smoke was seen rising from the crane truck used to restore large boulders back to the opened sea wall. The Contractor was reminded to well maintain all plants and equipment on site. Dark smoke, which indicates inefficient combustion of fuel within the plant engine, should be avoided to minimise air pollution emission.

Rev1 Page 3 of 4

Corrective Actions
Follow-up actions by the Contractor will be checked in next week's site inspection.
Signatures: ET:
(Name: Grace YANG)

Rev1 Page 4 of 4