



*Photo 1 – Hoarding fences of the new beach manhole have been dismantled and the site has been reinstated to its original conditions.*



*Photo 2 – Hoarding fences of the land duct have been dismantled and the site has been reinstated to its original conditions.*



*Photo 3 – Artificial Seawall in front of the cable landing point has been reinstated to its original conditions.*



*Photo 4 – Areas in vicinity of the cable landing point have been cleaned.*