



*Photo 1 - The silt curtain was decommissioned off the seawall.*



*Photo 2 - The construction site was found to be largely clean and tidy with rubbish seldom seen on site.*



*Photo 3 - Idling engines/plants were observed to be turned off.*



*Photo 4 - Stockpiles of the excavated materials were observed to be exposed.*