



*Photo 1 – Overview of the construction site at Tseung Kwan O Landing Point*



*Photo 2 – BHM fence Construction Work on-going*



*Photo 3 – Dusty construction material has been well covered by tarpaulin sheet.*



*Photo 4 – Contractor has been advised to cover the water bucket after use to prevent mosquitos breeding.*