



*Photo 1 - Overall view of beach manhole construction site during site inspection.*



*Photo 2 - Stockpiles of the excavated materials were observed to be exposed.*